

Product Name	Bossweld Argon Disposable Gas Bottle
Part Number	600032
SDS Document Number	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
Issue Date	05/12/25

## 1 Product identifier & identity for the chemical

### 1.1 Product Identifier

Product Name: Bossweld Argon Disposable Gas Bottle

Part Numbers: 600032

Synonyms: N/A

### 1.2 Other means of identification

N/A

### 1.3 Recommended use of the chemical and restrictions on use

Argon gas for welding. Not to be used for any other purpose.

### 1.4 Suppliers name, address and phone number

Supplier Name: Dynaweld Industrial Supplies Pty Ltd

Address: Building 2, 10 Jessica Place, Prestons NSW 2214, Australia

Phone: +61 2 8761 6500

Email: sales@dynaweld.com.au

Web Site: <https://www.dynaweld.com.au>

### 1.5 Emergency phone number

Emergency Phone: +61 2 8761 6500 (Australia)

## 2 Hazard Identification

### 2.1 Classification of the hazardous chemical

Press. Gas, H280 – Contains gas under pressure; may explode if heated.

### 2.2 Label elements, including precautionary statements

Signal Word: WARNING

Symbols:



Hazard Statements:

H280	Contains gas under pressure; may explode if heated
------	--

Precautionary Statements Storage

P410 + P403	Protect from sunlight. Store in a well-ventilated place.
-------------	--

### 2.3 Other hazards which do not result in classification

Asphyxiant in high concentrations.

The substance/mixture has no endocrine disrupting properties

Product Name	Bossweld Argon Disposable Gas Bottle
Part Number	600032
SDS Document Number	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
Issue Date	05/12/25

### 3 Composition/information on ingredients

#### 3.1 Identity of chemical ingredients

Chemical Name	CAS No.	Concentration Range (%)
Argon	(7440-37-1)	≥ 99.99

#### 3.2 CAS number and other unique identifiers

Note: See section 3.1

#### 3.3 Concentration of ingredients

Note: See section 3.1

### 4 First Aid Measures

#### 4.1 Description of necessary first aid measures

- General: If exposed or concerned get medical advice / attention. Get medical advice/attention if you feel unwell.
- Inhalation: If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Seek medical attention if breathing problems develop.
- Skin contact: Adverse effects not expected from this product.
- Eye contact: Adverse effects not expected from this product.
- Ingestion: Not considered a normal route of exposure.

#### 4.2 Symptoms caused by exposure

High concentrations may cause asphyxiation. Symptoms may include loss of mobility/consciousness. Victim may not be aware of asphyxiation.

Note: Refer to Section 11 for further information.

#### 4.3 Medical Attention and Special Treatment

Treat symptomatically.

### 5 Fire Fighting Measures

As shipped, this product is non-flammable. However, welding arc and sparks can ignite combustibles and flammable products. Read and understand *WTIA Technical Note No. 7 Health and Safety in Welding* before using this product.

#### 5.1 Suitable extinguishing media

- Water spray or fog.
- Product does not burn, use fire control measures appropriate for the surrounding fire.
- Do not use water jet to extinguish

#### 5.2 Specific hazards arising from the chemical

Fire exposure can cause the pressure to increase and the container may burst or explode. Use water to cool fire exposed containers.

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

### 5.3 Special protective equipment and precautions for fire fighters

Special protective equipment: Follow the general fire precautions indicated in the workplace. Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

Special precautions: Use firefighting procedures suitable for surrounding area. If safe to do so, remove containers from path of fire and prevent spillage from entering drains or water courses. May produce toxic fumes of metal oxides, poisonous fumes and corrosive fumes.

## 6 Accidental release measures

### 6.1 Personal precautions, protective equipment and emergency procedures

Evacuate unnecessary personnel. Ensure adequate air ventilation. Wear self-contained breathing apparatus when entering area, until safe.

*Note: Refer to recommendations in Section 8.*

### 6.2 Environmental precautions

If safe, try to stop release. Prevent from entering sewers or water courses, or anywhere accumulation can be dangerous.

### 6.3 Methods and materials for containment and cleaning up

If safe, try to stop release. Ensure adequate ventilation.

*Note/s: For further information, see Section 8. Refer to Section 13 for proper disposal.*

## 7 Handling and Storage

### 7.1 Precautions for safe handling

Do not eat, drink and/or smoke in the working areas or plants.

Use proper personal protective equipment such as safety shoes and gloves when handling cylinder.

Do not allow back feed into the cylinder.

Suck back of liquids into the container must be prevented.

Use only properly specified equipment that are suitable for this product.

Open slowly the valve to avoid pressure blows.

Avoid the direct contact of the product.

Container valve caps should be in place.

Handle carefully the cylinders, thus avoiding violent collisions between them or against other surfaces, as well as falls and other mechanical strains susceptible to damage their integrity/resistance.

### 7.2 Conditions for safe storage, including any incompatibilities

Observe all regulations and local requirements regarding storage of containers.

Store in cool, dry, and well ventilated place.

Containers should be stored in the vertical position and properly secured to prevent them from falling over.

Store cylinders in location free from fire risk and away from sources of heat and ignition.

Keep cylinders below 50°C in a well ventilated place.

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

## 8 Exposure controls/personal protection

### 8.1 Control parameters – exposure standards, biological monitoring

Use industrial hygiene monitoring equipment to ensure that exposure does not exceed the applicable national exposure limits.






Chemical Name	CAS No.	
Argon	(7440-37-1)	Asphyxiant

### 8.2 Appropriate engineering controls

Ventilation: Use enough ventilation, local exhaust at the arc, or both, to keep the fumes and gases below the exposure limits in the worker's breathing zone, and the general area. Keep exposure as low as possible.

*Note: See WTI Technical Note 7 – Health and Safety in Welding for further information / guidance.*

### 8.3 Personal protective equipment (PPE)

<b>Eye Protection</b>		Wear safety glasses with side shields or goggles.
<b>Hand protection:</b>		Wear protective gloves. Suitable gloves can be recommended by the glove supplier.
<b>Protective Clothing</b>		Wear hand, head, and body protection that will help to prevent injury from using this product. At a minimum this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats, shoulder protection, as well as dark substantial clothing. Wear dry gloves free of holes or split seams.
<b>Respiratory protection:</b>		Keep your head out of fumes. Use enough ventilation and local exhaust to keep fumes and gases from your breathing zone and the general area. Use respirable fume respirator, or air-supplied respirator when welding in confined space or where local exhaust or ventilation does not keep exposure below exposure limits.
<b>Hygiene measures:</b>		Do not eat, drink or smoke when using the product. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants.

*Note: See WTI Technical Note 7 – Health and Safety in Welding for further information / guidance.*

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

## 9 Physical and chemical properties

	Property	Product description
9.1	Appearance	Colourless gas
9.2	Odour	Odourless
9.3	Odour threshold	Odour threshold is subjective and is inadequate to warn of over exposure
9.4	pH	No further relevant information available
9.5	Melting point/freezing point	-189 °C. Freezing point not available.
9.6	Boiling point and boiling range	-186 °C.
9.7	Flash point	Not applicable
9.8	Evaporation rate	Not applicable
9.9	Flammability	Not applicable
9.10	Upper/lower flammability or explosive limits	Not applicable
9.11	Vapour pressure	Not applicable
9.12	Vapour density	Not applicable
9.13	Relative density (air = 1)	1.38
9.14	Solubility(ies)	67 mg/l
9.15	Partition coefficient: (n-octanol/water)	No further relevant information available
9.16	Auto-ignition temperature	No further relevant information available
9.17	Decomposition temperature	No further relevant information available
9.18	Viscosity	No further relevant information available
9.19	Specific heat value	No further relevant information available
9.20	Particle size	No further relevant information available
9.21	Volatile organic compounds content	No further relevant information available
9.22	% volatile	No further relevant information available
9.23	Saturated vapour concentration	No further relevant information available
9.24	Release of invisible flammable vapours and gases	No further relevant information available
	<b>Additional parameters</b>	
9.25	Shape and aspect ratio	No further relevant information available
9.26	Crystallinity	No further relevant information available
9.27	Dustiness	No further relevant information available
9.28	Surface area	No further relevant information available
9.29	Degree of aggregation or agglomeration	No further relevant information available
9.30	Ionisation (redox potential)	No further relevant information available
9.31	Biodurability or biopersistence	No further relevant information available

## 10 Stability and Reactivity

### 10.1 Reactivity

The product is non-reactive under normal conditions of storage and transport.

### 10.2 Chemical stability

Stable under normal conditions of storage and transport.

### 10.3 Conditions to avoid

Avoid heat, sparks, open flames, hot surfaces. Avoid moisture in installation systems

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

## 10.4 Incompatible materials and possible hazardous reactions

No reaction with any common materials in dry or wet conditions.

## 10.5 Hazardous decomposition products

Under normal conditions of storage and use, hazardous decomposition products should not be produced

## 11 Toxicological information

Acute Toxicity: no known toxicological effects from this product

Skin corrosion/irritation: Not classified

Serious eye damage/irritation: Not classified

Respiratory or skin sensitization: Not classified

Germ cell mutagenicity: Not classified

Carcinogenicity: Not classified

Reproductive toxicity: Not classified

Specific target organ toxicity (single exposure): Not classified.

Specific target organ toxicity (repeated exposure): Not classified.

Aspiration hazard: Not classified

### 11.1 Information on routes of exposure

**Inhaled:** Inhalation of dusts, generated by the material, during the course of normal handling, may be harmful. The inhalation of small particles of metal oxide results in sudden thirst, a sweet, metallic foul taste, throat irritation, cough, dry mucous membranes, tiredness and general unwellness. Headache, nausea and vomiting, fever or chills, restlessness, sweating, diarrhoea, excessive urination and prostration may also occur.

**Ingestion:** Not normally a hazard due to physical form of product. Considered an unlikely route of entry in commercial/industrial environments

**Skin Contact:** Skin contact does not normally present a hazard, though individuals may be found who react to substances usually regarded as inert. Molten material is capable of causing burns.

**Eye:** Fumes from welding/brazing operations may be irritating to the eyes.

**Chronic:** Principal routes of exposure include accidental contact with the molten metal and inhalation of fume arising as a consequence of the action of the flame on the rod / wire. Although fume generation rates are generally low, excessive heating of the material, well above its quoted melting point, may result in over-exposure.

### 11.2 Symptoms related to exposure

*Note: See Section 11.1*

### 11.3 Numerical measures of toxicity

No further information available

### 11.4 Immediate, delayed and chronic health effects from exposure

*Note: See Section 11.1*

### 11.5 Exposure Levels

*Note: See Section 11.1*

### 11.6 Interactive effects

*Note: See Section 11.1*

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

## 11.7 Data limitations

No further information available.

## 12 Ecological information

Welding consumables and materials could degrade / weather into components originating from the consumables or from the materials used in the welding process. Avoid exposure to conditions that could lead to accumulation in soils or groundwater.

### 12.1 Ecotoxicity

No further relevant information available.

### 12.2 Persistence and degradability

No further relevant information available.

### 12.3 Bioaccumulative potential

No further relevant information available.

### 12.4 Mobility in soil

No further relevant information available.

### 12.5 Other adverse effects

No further information available.

## 13 Disposal considerations

### 13.1 Safe handling and disposal methods

Do not discharge into any place where its accumulation could be dangerous, but in atmosphere or well ventilated area. Gas cylinders are not refillable. Dispose according to applicable local and state government regulations.

### 13.2 Disposal of any contaminated packaging

Dispose according to applicable local and state government regulations.

### 13.3 Environmental regulations

Consult State Land Waste Management Authority for more information.

## 14 Transport information

No international regulations or restrictions are applicable.

### 14.1 UN number

UN 1006

### 14.2 Proper shipping name

ARGON COMPRESSED

### 14.3 Transport hazard class(es)

2.2

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

#### 14.4 Packing group

No further relevant information available

#### 14.5 Environmental hazards

No further relevant information available

#### 14.6 Special precautions during transport

No further relevant information available

#### 14.7 Hazchem Code

2T

#### 14.8 Additional Information

##### Sea Transport

EMS: F-C, S-V

Proper Shipping Name: ARGON, COMPRESSED

##### Air Transport

Cargo

Pkg Inst: 200

Max Net Qty/Pkg: 150kg

Passenger

Pkg Inst: 200

Max Net Qty/Pkg: 75kg

ERG Code: 2L

## 15 Regulatory information

### 15.1 Safety, health and environmental regulations specific for the product in question

Regulations of each country are applied to substances / mixtures.

<b>Australian Inventory of Chemical Substances</b>	
7440-37-1	Argon

### 15.2 Poisons Schedule number

A poison schedule number has not been allocated to this product using the criteria in the Standard for the Uniform Scheduling of Medicines and Poisons (SUSMP).

<b>Product Name</b>	Bossweld Argon Disposable Gas Bottle
<b>Part Number</b>	600032
<b>SDS Document Number</b>	SDS_Bossweld_Argon Gas Bottle_V1.2_051225
<b>Issue Date</b>	05/12/25

## 16 Other information

Training advice: Ensure that user is aware of the potential hazards and knows what to do in the event of an accident or an emergency.

### 16.1 Date of preparation or review

5<sup>th</sup> December, 2025

### 16.2 Key abbreviations or acronyms used

BEI - Biological Exposure Indices

GHS - Globally Harmonized System of classification and labelling of chemicals.

IARC - International Agency for Research on Cancer

NTP - National Toxicology Program

PPE - Personal Protection Equipment

SUSMP - Standard for the Uniform Scheduling of Medicines and Poisons

TLVs - Threshold Limit Value

WTIA – Welding Technology Institute of Australia

Dynaweld Industrial Supplies Pty Ltd requires that all customers read this safety data sheet carefully so as to be informed about the risks implied in the use of the product, and provide any person involved with a copy of the same and/or adequate training on the use of the product.

Whilst Dynaweld Industrial Supplies Pty Ltd has taken all due care to include accurate and up-to-date information in this SDS, it does not provide any warranty as to accuracy or completeness. As far as lawfully possible, Dynaweld Industrial Supplies accepts no liability for loss, injury or damage (including consequential loss) which may be suffered or incurred by any person as a consequence of their reliance on the information contained in the SDS,

**END OF SAFETY DATA SHEET**